

Technical Service Report

Date 11/12/23

Dealer GHS

Site Name El Jiannah Prestons

Site Address R046-047 Corner Bernera & Yato Roads, Prestons, NSW, 2170

Warranty Yes ~~No~~

Issue New unit. Just delivered. Not working. High Temp

Tech went out Thursday night.

Fixed on Monday morning with compressor delivered.

Technician Phong

Model KSR18-3-N

Serial Number H2KS18317005

Fixed Yes ~~No~~

Work done to fix Compressor drawing high amp and tripped out on overload, also cables were broken sometimes connecting and sometimes not.

Spare parts used Compressor, filter drier, Mainboard

NOTE : 2 invoices. 1 for initial check up then another to replace the compressor