

Technical Service Report

Date 11/12/23

Dealer GHS

Site Name Mani Milson point

Site Address Shop 1, 118 Alfred St Milsons Point

Warranty Yes ~~No~~

Issue Not working

Technician Phong

Model KUR15-2-N

Serial Number H2KU152H9028

Fixed Yes ~~No~~

Work done to fix Capacitor was changed

Spare parts used Start Capacitor